
Mains branch mechanical connector with moisture / contaminant block

MECHANICAL CONNECTORS



MB18 Connectors



Principle Application

For mains branch jointing of aluminium / copper, stranded / solid circular conductor cores.

Range

| PRODUCT REFERENCE | STRANDED CORE C.S.A. (mm²) | | | | |
|----------------------|----------------------------|---------|------------|---------|--|
| | MAIN | | BRANCH/TAP | | |
| | MINIMUM | MAXIMUM | MINIMUM | MAXIMUM | |
| MB18/1 | 35 | 95 | 35 | 95 | |
| MB18/2 | 95 | 150 | 35 | 95 | |
| MB18/3 | 95 | 150 | 95 | 150 | |
| MB18/EDF | 95 | 240 | 95 | 240 | |
| MB18/4 | 185 | 240 | 35 | 95 | |
| MB18/5 | 185 | 240 | 185 | 240 | |
| MB18/6 | 185 | 240 | 95 | 150 | |
| MB18/7 | 95/150 | 185/240 | 95 | 150 | |
| MB18/8 | 35/95 | 95/150 | 35 | 95 | |

Note: For jointing other core configurations/sizes please contact Sicame Technical Dept

The **Hepworth MB18** range of mechanical connectors provide an integral moisture/ contaminant block thereby removing the possibility of migration of contaminants/moisture across the joint.

The range of connectors utilise the Hepworth shear head technology in the form of direct acting clamping bolts.





Mains branch mechanical connector with moisture / contaminant block


MECHANICAL CONNECTORS

MB18 Connectors

Physical Dimensions







| PRODUCT | DIMENSIONS (mm) | | | | |
|-----------|-----------------|----|------|-----------|--|
| REFERENCE | A | В | С | D | |
| MB18/1 | 116 | 61 | 30.5 | 13 A/F | |
| MB18/2 | 116 | 61 | 30.5 | 13/17 A/F | |
| MB18/3 | 116 | 61 | 30.5 | 17 A/F | |
| MB18/EDF | 116 | 61 | 30.5 | M16 (UNI) | |
| MB18/4 | 125 | 76 | 37.5 | 13/19 A/F | |
| MB18/5 | 125 | 76 | 37.5 | 19 A/F | |
| MB18/6 | 125 | 76 | 37.5 | 19/17 A/F | |
| MB18/7 | 125 | 76 | 37.5 | 19/17 A/F | |
| MB18/8 | 116 | 61 | 30.5 | 13/17 A/F | |

Material

Aluminium Alloy

Test Specification

Designed to meet the requirements of Engineering Recommendation C79 and IEC 1238-1.

Fitting instructions

- 1. Strip the primary insulation from each core equal to the depth of the bore + 5mm.
- 2. Thoroughly abrade exposed conductor cores.
- 3. When jointing copper conductor cores, wrap the supplied brass gauze around the core before insertion.
- 4. Fully insert the conductor core into the connector body.
- 5. Torque tighten the shear bolts alternatively, one turn at a time, until both bolt heads have sheared.

