



Single Core Heat Shrink Joints 7.2 to 33kV



Single Core XLPE 7.2/12kV Joints

Part Number	Voltage	Cable Range
SPJ 12X-25-70-1	12kV	25-70mm ²
SPJ 12X-95-185-1	12kV	95-185mm ²
SPJ 12X-185-300-1	12kV	185-300mm ²
SPJ 12X-400-630-1	12kV	400-630mm ²
SPJ 12X-800-1	12kV	800mm ²

Single Core XLPE 17.5kV Joints

Part Number	Voltage	Cable Range
SPJ 17.5X-25-70-1	17.5kV	25-70mm ²
SPJ 17.5X-95-185-1	17.5kV	95-185mm ²
SPJ 17.5X-185-300-1	17.5kV	185-300mm ²
SPJ 17.5X-400-630-1	17.5kV	400-630mm ²
SPJ 17.5X-800-1	17.5kV	800mm ²

Single Core XLPE 24kV Joints

Part Number	Voltage	Cable Range
SPJ 24X-25-70-1	24kV	25-70mm ²
SPJ 24X-95-185-1	24kV	95-185mm ²
SPJ 24X-185-300-1	24kV	185-300mm ²
SPJ 24X-400-630-1	24kV	400-630mm ²
SPJ 24X-800-1	24kV	800mm ²


Single Core XLPE 33kV Joints

Part Number	Voltage	Cable Range
SPJ 36X-25-70-1	33kV	25-70mm ²
SPJ 36X-95-185-1	33kV	95-185mm ²
SPJ 36X-185-300-1	33kV	185-300mm ²
SPJ 36X-400-630-1	33kV	400-630mm ²

Notes: If cable is armoured (AWA), armour earth kit is supplied and part number becomes SPAJ. If long cable runs, cross bonding kits may be required, see page 29 for details.



Single Core Heat Shrink Joints 7.2 to 33kV



Single Core PILC 12kV Joints

Part Number	Voltage	Cable Range
SPJ 12P-50-95-1	12kV	50-95mm ²
SPJ 12P-120-185-1	12kV	120-185mm ²
SPJ 12P-240-400-1	12kV	240-400mm ²
SPJ 12P-500-630-1	12kV	500-630mm ²

Single Core PILC 33kV Joints

Part Number	Voltage	Cable Range
SPJ 36P-50-95-1	33kV	50-95mm ²
SPJ 36P-120-185-1	33kV	120-185mm ²
SPJ 36P-240-400-1	33kV	240-400mm ²
SPJ 36P-500-630-1	33kV	500-630mm ²

Single Core PILC to XLPE 12kV Joints

Part Number	Voltage	Cable Range
SPJ 12PX-50-95-1	12kV	50-95mm ²
SPJ 12PX-120-185-1	12kV	120-185mm ²
SPJ 12PX-240-400-1	12kV	240-400mm ²
SPJ 12PX-500-630-1	12kV	500-630mm ²

Single Core PILC to XLPE 33kV Joints

Part Number	Voltage	Cable Range
SPJ 36PX-50-95-1	33kV	50-95mm ²
SPJ 36PX-120-185-1	33kV	120-185mm ²
SPJ 36PX-240-400-1	33kV	240-400mm ²
SPJ 36PX-500-630-1	33kV	500-630mm ²

Notes: If cable is armoured (AWA), armour earth kit is supplied and part number becomes SPAJ. If long cable runs, cross bonding kits maybe required, see page 29 for details.